



# PSP Detailed Report

Federal Motor Carrier Safety Administration  
Burton Litton

File #: 1250343      Date: 10/4/2023 2:09:41 PM

### Driver Information

Last Name	First Name	License #	State
LITTON	BURTON	PA2336558	PA

### Crash Activity (5 year history from MCMIS snapshot date)

**Crash Summary** (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility)

# of Crashes:	2	# of Crashes with Fatalities:	0	# of Crashes with Injuries:	1	# of Towaways:	2
# Not preventable	1	# of Fatalities:	0	# of Injuries:	2	# of Hazmat Releases:	0

**Crash Details** (Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility)

Date	Dot #	Carrier Name	Driver Name	Drivers Lic	State	Driver DOB	Rpt St	Rpt Number	Location	Injuries	Fatalities
06/15/2021	513264	Motor Transport	LITTON, BURTON	PA2336558	PA	08/21/1958	PA	PA707338100X	ROUTE 0051 N	0	0
- REVIEWED - NOT PREVENTABLE - FMCSA REVIEWED THIS CRASH AND DETERMINED THAT IT WAS NOT PREVENTABLE.											
10/04/2021	227058	ABC Carrier	LITTON, BURTON	PA2336558	PA	08/21/1958	PA	PA909965500X	ROUTE 8033 S	2	0

### Inspection Activity (3 year history from MCMIS snapshot date)

#### Driver Summary

#### Vehicle Summary

#### Hazmat Summary

Driver Inspections:	3	Vehicle Inspections:	3	Hazmat Inspections:	0
Driver Out-of-service Inspections:	0	Vehicle Out-of-service Inspections:	1	Hazmat Out-of-service Inspections:	0
Driver Out-of-service Rate:	0	Vehicle Out-of-service Rate:	33	Hazmat Out-of-service Rate:	0

### Inspection Details

Carrier Info			Driver Info				Inspection Info					
Date	Dot #	Carrier Name	Driver Name	Drivers Lic	State	Driver DOB	Rpt St	Rpt Number	HazMat Insp	Insp Level	# of Viol	
04/12/2021	113693	Roberts Trucking	LITTON, BURTON	PA2336558	PA	08/21/1958	CT	2700005152	N	2	3	
			Driver Violation: 392.2	Local laws (general)			NON-OOS					
			Vehicle Violation: 393.75(a)	Flat tire or fabric exposed			OOS					

		Vehicle Violation: 393.205(a)	Wheel/rim cracked or broken	NON-OOS							
05/02/2021	113693	Big Rigs Carriers	LITTON, BURTON	PA2336558	PA	08/21/1958	PA	UCJ6000843	N	4	0
05/06/2021	113529	We Drive U	LITTON, BURTON	PA2336558	PA	08/21/1958	TX	083J0BCO01	N	2	2
		Driver Violation: 392.2S	Speeding	NON-OOS							
		Vehicle Violation: 393.75(a)(1)	Tire-ply or belt material exposed	NON-OOS							
11/03/2021	113529	XYZ Trans	LITTON, BURTON (co-driver)	PA2336558	PA	08/21/1958	NY	D010003932	N	2	0

### Violation Summary

Violation #	Description	# of Violations	# of Out of Service Violations
392.2	Local laws (general)	1	0
393.75(a)	Flat tire or fabric exposed	1	1
393.205(a)	Wheel/rim cracked or broken	1	0
392.2S	Speeding	1	0
393.75(a)(1)	Tire-ply or belt material exposed	1	0

This summary counts and rates only include violations that were attributable to LITTON, BURTON

### Additional Driver Names & Licenses

Last Name	First Name	License #	State
LITTON	BURTON	PA2336558	PA

For an explanation of FMCSA-reportable crashes see <https://www.psp.fmcsa.dot.gov/psp/Faqs>

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

StarPoint Screening, The LIG Group LLC: 877-330-2444, info@starpointscreening.com