

PSP Detailed Report

Federal Motor Carrier Safety Administration

Burton Litton

File #: XXXXXXXX

Date: 10/4/2023 2:09:41 PM

_				
IJ	riva	r Ini	nrm	ation

Last Name	First Name	License #	State
LITTON	BURTON	PA2336558	PA

Crash Activity (5 year history from MCMIS snapshot date)

(Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility) Crash Summary

2 2 # of Crashes: # of Crashes with Fatalities: 0 # of Crashes with Injuries: 1 # of Towaways: 0 2 0 # Not preventable # of Fatalities: # of Injuries: # of Hazmat Releases:

(Crashes listed represent a driver's involvement in FMCSA-reportable crashes, without any determination as to responsibility) **Crash Details**

Date	Dot#	Carrier Name	Driver Name	Drivers Lic	State Driver DOB Rpt St Rpt Number Location	Injuries Fatalities
06/15/2021	513264	Motor Transport	LITTON, BURTON	PA2336558	PA 08/21/1958 PA PA707338100X ROUTE 0051	0 0

- REVIEWED - NOT PREVENTABLE - FMCSA REVIEWED THIS CRASH AND DETERMINED THAT IT WAS NOT PREVENTABLE.

10/04/2021 227058 **ABC Carrier** LITTON, BURTON PA2336558 PA909965500X ROUTE 8033 S 2 PA 08/21/1958 PA

Inspection Activity (3 year history from MCMIS snapshot date)

Driver Summary		Vehicle Summary		Hazmat Summary		
Driver Inspections:	3	Vehicle Inspections:	3	Hazmat Inspections:	0	
Driver Out-of-service Inspections:	0	Vehicle Out-of-service Inspections:	1	Hazmat Out-of-service Inspections:	0	
Driver Out-of-service Rate:	0	Vehicle Out-of-service Rate:	33	Hazmat Out-of-service Rate:	0	

Inspection Details

Carrier Info Driver Info			Inspection Info						
Date	Dot #	Carrier Name	Driver Name	Drivers Lic	State Driver DOB	Rpt St Rpt Number	HazMa Insp		# of Viol
04/12/2021	113693	Roberts Trucking	LITTON, BURTON	PA2336558	PA 08/21/1958	CT 2700005152	N	2	3

Driver Violation: 392.2 Local laws (general) NON-OOS

Vehicle Violation: 393.75(a) Flat tire or fabric exposed oos

Report executed at: 10/4/2023 2:09:41 PM MCMIS snapshot date: 07/18/2023

		Vehicle Violation: 393.205(a)	Wheel/rim cracked or broken			N	ON-OC	s			
05/02/2021	113693	Big Rigs Carriers	LITTON	I, BURTON	PA2336558	PA	08/21/1958	PA	UCJ6000843	N	4	0
05/06/2021	113529	We Drive U	LITTON	I, BURTON	PA2336558	PA	08/21/1958	TX	083J0BCO01	N	2	2
		Driver Violation: 392.2S	4)	Speeding				ON-OC				
		Vehicle Violation: 393.75(a)(1)	Tire-ply or belt material exposed			IN	ON-OC	15			
11/03/2021	113529	XYZ Trans	LITTON (co-driv	I, BURTON <mark>er)</mark>	PA2336558	PA	08/21/1958	NY	D010003932	N	2	0

Violation Summary

Violation #	Description	# of Violations	# of Out of Service Violations
392.2	Local laws (general)	1	0
393.75(a)	Flat tire or fabric exposed	1	1
393.205(a)	Wheel/rim cracked or broken	1	0
392.2S	Speeding	1	0
393.75(a)(1)	Tire-ply or belt material exposed	1	0

This summary counts and rates only include violations that were attributable to LITTON, BURTON

Additional Driver Names & Licenses

Last Name	First Name	License #	State
LITTON	BURTON	PA2336558	PA

For an explanation of FMCSA-reportable crashes see https://www.psp.fmcsa.dot.gov/psp/Faqs

This document contains sensitive information. Improper handling of this information can negatively affect individuals. Handle and secure this information appropriately to prevent inadvertent disclosure by keeping the document under the control of authorized persons. Properly dispose of this document when no longer required.

StarPoint Screening, The LIG Group LLC: 877-330-2444, info@starpointscreening.com

